

FIG. 5




FIG. 6 Source Target MS Source Target MSC PDSN BSC BSC PŒ PCF 76 77 178 79 Dormant, PPP connection is maintained Origination Message LBI \ 82 BS Ack Order 83 CM Service Req 84 T₃₀₃ Assignment Req 185 A9-Setup-A8 87 186 T_{A8-ætup} T_{10} PDSN Dommant HO Procedures 2.16.5.8 A9-Release-A8 Complete Assignment Failure 88 91 Dormant Packet Data Session Clear com (Auth. Failed for domant MS) **Authentication** 92 resultsreceived 93 indicating failure 95 A9-update 94 A10 release procedures A9-update Ack 196 Clear complete

FIG. 7





FIG. 8



F16. 9

